



Aircraft Trading

Plane & Simple

1992 Learjet 35A

Serial Number: 672

Registration: XA-FMT



RVSM, Dee Howard Thrust Reversers, 36 Inch Cargo Door
Lowest Time 35A on the Market!

Airframe and Engines: (as of 1/15/08)


Airframe Total Time: 1306.3

	S/N	SNEW
Engine #1	P-89736	1306.3
Engine #2	P-89735	1306.3

Exterior: Matterhorn white with three emerald green stripes. Though factory original, this paint is rated a 7.5 due to low usage and always being hangered.

**VERIFICATION OF SPECIFICATIONS REMAIN SOLE RESPONSIBILITY OF PURCHASER
AIRCRAFT SUBJECT TO PRIOR SALE AND REMOVAL FROM THE MARKET**

World Aircraft Trading, Inc., 6941 N. Trenholm Rd., Suite F-105, Columbia, SC 29206
Office: 803-743-9602 www.worldaircrafttrading.com Fax: 803-743-9420



Aircraft Trading

Plane & Simple



Avionics: Dual Collins FIS-84 2-tube EFIS
Dual Collins VHF-22A COMMS
Dual Collins VIR-32 NAVS
Dual Collins DME-42
Dual Collins ADF-60
Dual Collins TDR-90 Transponder
Collins ALT-55B Radar Altimeter
J.E.T. FC-530 Auto Pilot
Sperry Primus 450 Color Radar
Wulfsberg VI Flight Phone
King KHf-950 HI FREQ
Fairchild A100 CVR
Universal UNS-1B w/ GPS Long Range NAV
Honeywell TAWS
Mark VIII EGPWS

**VERIFICATION OF SPECIFICATIONS REMAIN SOLE RESPONSIBILITY OF PURCHASER
AIRCRAFT SUBJECT TO PRIOR SALE AND REMOVAL FROM THE MARKET**

World Aircraft Trading, Inc., 6941 N. Trenholm Rd., Suite F-105, Columbia, SC 29206
Office: 803-743-9602 www.worldaircrafttrading.com Fax: 803-743-9420



Aircraft Trading

Plane & Simple



Interior: 2004, Beige barber carpet, rich burgundy leather seats, Ultrasuede Headliner, Walnut Woodwork. B & D Cabin Display. Forward Refreshment Center.

**VERIFICATION OF SPECIFICATIONS REMAIN SOLE RESPONSIBILITY OF PURCHASER
AIRCRAFT SUBJECT TO PRIOR SALE AND REMOVAL FROM THE MARKET**

World Aircraft Trading, Inc., 6941 N. Trenholm Rd., Suite F-105, Columbia, SC 29206
Office: 803-743-9602 www.worldaircrafttrading.com Fax: 803-743-9420



Aircraft Trading

Plane & Simple



**VERIFICATION OF SPECIFICATIONS REMAIN SOLE RESPONSIBILITY OF PURCHASER
AIRCRAFT SUBJECT TO PRIOR SALE AND REMOVAL FROM THE MARKET**

World Aircraft Trading, Inc., 6941 N. Trenholm Rd., Suite F-105, Columbia, SC 29206
Office: 803-743-9602 www.worldaircrafttrading.com Fax: 803-743-9420



Aircraft Trading

Plane & Simple

Inspection Status: 12 Year completed 4/21/2004 by Saberliner Corp.

3, 6, 12, & 24 Month, 300 hour, 600 hour, Phase A1A, A6, B1A, B6, Flapper Movement in Tip Tanks inspected Sept. 7, 2007 by Taller Aeronautico Autorizado.

Transponder, Altimeter, Pitot Static, and 24 Month inspected April 16, 2006.



**VERIFICATION OF SPECIFICATIONS REMAIN SOLE RESPONSIBILITY OF PURCHASER
AIRCRAFT SUBJECT TO PRIOR SALE AND REMOVAL FROM THE MARKET**

World Aircraft Trading, Inc., 6941 N. Trenholm Rd., Suite F-105, Columbia, SC 29206
Office: 803-743-9602 www.worldaircrafttrading.com Fax: 803-743-9420